



GARY R. HERBERT  
Governor  
SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Minerals Inspection Report

Report Date: 07/08/2014

Reviewed

Mine Name: Blind Stream 5-11 Honeycomb	Permit Number: S/013/0004	Mine Status: Active
Operator Name: Floyd Anderson - Shamrock	Inspection Date: 06/25/2013	Permit Fees: Paid
Inspector(s): L. Heppler	Inspection Time: PM	Bond Amount: \$25,300
Attendee(s): Dave Herron - USFS, Tom Hycroft and others	Weather: Cool, Dry	Bond Escalation: 12/22/2014
Inspection Purpose: Routine annual inspection		Prior Inspection: 09/28/2010

### Conclusions and Recommendations

Current bond is for a 5 acre site. The purpose of the inspection was to meet a new operator who was interested in transferring the current permit. Site needs to be surveyed to confirm acreage.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Permit fee is up to date, no transfers have been requested, but discussed on site, bond escalation is due as shown above.		
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
There is a locked gate at the entrance of the road, there are no underground workings, but there is a highwall.		
3. <i>Protection of Drainages/Erosion Control</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No erosional problems were noted, but weather was dry		
4. <i>Deleterious Material</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
There were several petroleum spills at the site, USFS requested clean-up per their requirements		
5. <i>Roads (maintenance, surfacing, dust control, safety)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Roads were rough, but are adequate to access the site. It appears there are a few localized areas along the road that have been improved		
6. <i>Reclamation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No reclamation has been started, there was discussion on site with the operator regarding doing concurrent reclamation to reduce the disturbance area and bond amount.		
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No regrading or backfilling was noted at the site at the time of the inspection		
8. <i>Soils</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Separate soil stockpiles were not noted on site, it appeared as if soil was blended, with waste rock.		
9. <i>Revegetation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
There has been no efforts to revegetate the site		
10. <i>Other</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
This line is intentionally left blank		

Inspector's Signature:

CC: Floyd Anderson - ShamrockMining associates, LLC, USFS-DAHerron@FS.Fed.US

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M013-Duchesne/S0130004-Shamrock/inspections/INSP-06252013.pdf





Gate for access to mine site



New laydown yard



Overview - Mine highwall



Overview - Mine highwall